


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 2/1996 To (mo./yr.) 2/1997
 2. DOGM File Number (Mine No): 510231028 umc 128384-128387
 3. Mine Name: Treasure Chest 1 Through #1
 4. Mineral(s) Mined (or permitted to mine): Geodes
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
SE 1/4, ___ 1/4, Section 1, Township 11S, Range 12W
~~SW~~ 1/4, ___ 1/4, Section ~~1~~, Township ~~11S~~, Range ~~12W~~
~~NE~~ 1/4, ___ 1/4, Section ~~12~~, Township ~~11S~~, Range ~~12W~~
 7. Name of Operator or Company: Loy D Crapo
 8. Permanent Street Address: 350 East 300 South 70 Box 113
City, State, Zip: Delta, Utah 84624
Phone: 864-2402
 9. Company Representative (or designated operator):
Name: _____
Title: same as above
Business Address: _____
City, State, Zip: _____
Phone: _____
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 10 Ton Geodes

3. How much additional acreage was disturbed during the past year? _____
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

We Disturbed a very small area because we dug
in The same Hole mostly going deeper.
we also plan to dig a Hole for small Geodes
about 100 yard East of existing Diggings.

5. How much acreage was reclaimed during the past year? none
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

7. What is the total disturbed acreage at years end? less Than 5 acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

we plan to Reclaim all small Holes
on The East Side of Dipping area

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Loy D. Crapo

Title of Operator:

Signature of Operator:

Date:

Loy D. Crapo
2/26/96